

Nebraska Department of Water, Energy, and Environment

The National Emission Standards for Hazardous Air Pollutants (NESHAP) and New Source Performance Standards (NSPS) notebooks are to be used as an assistance tool to help comply with state and federal regulations. The Notebooks are not inclusive and are not meant to serve as a substitute for compliance with all applicable regulations. If you have corrections, comments, or questions regarding the notebooks, NSPS, NESHAP or permitting, please contact us at DWEE.AirQuality@nebraska.gov or 402-471-2186.

Air Toxics Notebook

Phosphoric Acid Manufacturing

eCFR 40 CFR Part 63 Subpart AA

40 CFR Part 63 Subpart AA	Phosphoric Acid Manufacturing
Amendment Dates	11/03/2020 09/28/2017 08/19/2015
Am I Subject to this subpart?	I. This subpart applies to: (A) Affected sources at phosphoric acid manufacturing plants that are Major Sources of HAPs*. (B) Affected sources: (1) Wet-process phosphoric acid process lines; (2) Evaporative cooling towers; (3) Phosphate rock dryers; (4) Phosphate rock calciners; (5) Superphosphoric acid process lines; (6) Purified phosphoric acid process lines; (7) Gypsum dewatering stacks; (8) Cooling ponds. II. Not Subject to this Subpart: (A) Research and development facilities. (B) Phosphoric acid manufacturing plants considered area sources *Major Sources of HAPs emit or have the potential to emit: (1) ≥ 10 tons/year of any single HAP; or (2) ≥ 25 tons/year of total HAPs.
Related Rules	NESHAP - 40 CFR Part 63 Subpart BB - Phosphate Fertilizers Production Plants
Page Last Updated	07/01/2025